



WALL BASE FLASHING (BRIDGING CONDITION) - STEP I

- FOLLOWING ARE LIMITED OUTLINE NOTES TO REPAIR ABOVE AREAS. REFER TO CARLISLE SPECIFICATION FOR MEANS AND METHOD TO MAKE REPAIRS.
- INSPECT EXISTING BASE FLASHING AT RISING WALL AND MARK AREAS WHERE MEMBRANE IS STRETCHED OR UNBONDED FROM THE CORNER. REINFORCED UNIVERSAL SECURMENT STRIP (RUSS) OR WALL
- 'n REMOVE STONE ON BALLASTED ROOF AREAS AS NEEDED.
 CAREFULLY INSPECT FOR CUTS, HOLES, PUNCTURES OR SIMILAR
 CONDITIONS PRIOR TO RINSING THE MEMBRANE. AT SUCH CONDITIONS, INSTALL A TEMPORARY PATCH.
- WITHIN DEFICIENT AREA, CLEAN THE RECEIVING AREA PRIOR TO CUTTING OF MEMBRANE TO KEEP THE INSULATION DRY. CLEAN WITH CARLISLE'S SPECIFIED CLEANING SOLUTION AND THOROUGHLY CLEAN WITH WARM WATER TO RINSE AFTER CLEANING.

WALL BASE FLASHING (BRIDGING CONDITION) - STEP 2

Ġ, INSPECT FOR THE PRESENCE OF MOISTURE AT EXPOSED OUT IN INSULATION AREAS AND REPLACE WET INSULATION TO MATCH IN KIND & THICKNESS WITH EXISTING.

CUT OUT THE SLACKED OR TENTED PORTION OF MEMBRANE.

্দ


- .1 CLEAN THE ENTIRE BASE FLASHING AT RECEIVING AREAS
- ò APPLY PRIMER AND 6" WIDE SECURTAPE
- 9. INSTALL NEW EPDM MEMBRANE FLASHING
- IO. ROLL THE SPLICE WITH A 2" WIDE STEEL ROLLER AND APPLY LAP SEALANT.



VERTICAL TRANSITIONS OR RISING FLASHING TENTING CONDITION AT

523 FOR APPLICABLE ADDITIONAL INFORMATION, SEE PAGES OR DETAIL(S): EGENDI.3. 5.2.2

DETAIL EPDM ROOF RESTORATION




FLASHING WITH BATTEN
ATTACHMENT - PAGE 1 OF 3. (SEE 5.2.2
& 5.2.3 FOR 3D VIEWS.

ADDITION SEE NIFORMATION SEE PAGES OR DETAIL(5).
5.2.2 5.2.3

EGENDI.3.

N SEE DETAIL

5.2.1





WITH WOOD BATTEN


(PARTIAL OR SPOT REPAIR)

3-D VIEW OF DETAIL 5.2.1 'A' & 'B'

FOR APPLICABLE
ADDITIONAL
INFORMATION, SEE
PAGES OR
DETAIL(S):

ECENDI3.

EPDM ROOF RESTORATION
DETAIL |






3-D VIEW OF DETAIL 5.2.1 'C'

FOR APPLICABLE
ADDITIONAL
INFORMATION, SEE
PAGES OR
DETAIL(5): 5.2.2

EGENDI.3.

EPDM ROOF RESTORATION
DETAIL |

© 2007 CARLISLE SYNTEC INCORPORATED



NOTES:

- PRIOR TO ANY WORK, COORDINATE WITH THE OWNER TO DISCOVER ANY LEAKS OR HISTORY OF LEAKS AT AREAS BELOW. IF LEAK(S) EXISTS, DO NOT INSTALL THIS FLASHING AND CONDUCT A THOROUGH INSPECTION TO VERIFY THE CAUSES OF LEAKS. INSTALLATION OF THIS DETAIL MAY WORSEN THE LEAK CONDITION IF EXISTING CONDITIONS ARE NOT COMPLETELY ANALYZED.
- IF NO LEAKS EXIST, THEN INSPECT THE EXISTING CONDITIONS OF THE FLASHING AND LOOK FOR THE FOLLOWING ITEMS:

'n

COMPOSITION.

IDENTIFY THE TYPE OF SUBSTRATE WALL AND ITS CONSTRUCTION

UNDERSTAND THE EXISTING INSTALLATION DETAIL ¢ ITS DRAINAGE

ö


- ? ENSURE THERE ARE NO WEEP HOLES ABOVE THE TOP OF TERMINATION BAR AREA THAT SHOULD NOT BE COVERED WITH NEW FLASHING (PARTICULARLY WHERE STEEP SLOPED ROOF EXIST AND MASONRY THROUGH WALL FLASHING IS BUILT IN STEPS), AVOID COVERING WEEPS IN THIS CONDITION ALSO.
- ٩ IF THERE ARE HAIRLINE CRACKS, OPEN JOINTS OF WALL SYSTEMS, OPEN HEAD JOINTS IN MASONRY, OR SIMILAR CONDITIONS THAT MAY HELP THE MIGRATION OF WATER, COORDINATE WITH THE CONSULTANT TO RESOLVE THESE ISSUES PRIOR TO INSTALLATION OF REMEDIAL
- Ġ VERTICALLY STAGGER NEW NAILING PATTERN WITH EXISTING TO AVOID SECUREMENT IN THE SAME AREA). DEVELOPMENT OF CRACKS IN THE SUBSTRATE (DUE TO ADDITIONAL
- VERIFY IF THERE ARE LOOSE NAILS/SCREWS WHICH ARE PROTRUDING AND RESET THEM PRIOR TO NEW FLASHING INSTALLATION.
- 'n AT THE JUNCTION OF PARAPET & RISING WALLS, COORDINATE WITH CONSULTANT TO RESOLVE THE UNSIGHTLY APPEARANCE OF NEW FLASHING ABOVE PARAPET WALL.
- AT EXPANSION JOINTS, SEALANT TO BE REPAIRED/REPLACED BY OTHERS
- ৸ ENSURE SUBSTRATE IS DRY, SMOOTH & STRUCTURALLY SOUND. WHERE COMMON GRADE BRICKS ARE SPALLING OR DETERIORATED TO UNACCEPTABLE LEVEL, THERE REPLACE COMMON GRADE BRICKS WITH NEW SM-GRADE (SEVERE MEATHER GRADE) BRICKS. THE MASONRY MUST BE REPLACED BY OTHERS TO ACHIEVE A SOUND SUBSTRATE.



TERMINATION BAR RESTORATION OF FLASHING AT

FOR APPLICABLE ADDITIONAL INFORMATION, SEE PAGES OR DETAIL(S): EGENDI.3.

DETAIL EPDM ROOF RESTORATION




© 2001 CARLISLE SYNTEC INCORPORATED

Carlisle SynTec Incorporated

OUTSIDE CORNER FLASHING RESTORATION DETAIL

EGENDI.3.1





RESTORATION DETAIL INSIDE CORNER FLASHING

EGEND 1.3.1

EPDM ROOF RESTORATION
DETAIL |