VERSICO
ROOFING SYSTEMS

PRODUCT
UPDATE

Update – Tooele, UT, Polyiso Production (ReadyFlash® Availability)
June 2026

To: Versico Roofing Systems' Authorized Contractors


Due to current GRF facer supply constraints, materials produced at this facility will temporarily ship without ReadyFlash Technology. During this period, you may receive boards with either black facer on both sides or tan facer on both sides. The black facer provided during this time is not part of our ReadyFlash offering and does not deliver the same heat-absorption characteristics associated with ReadyFlash requirements.

We are actively working to restore normal supply and resume full ReadyFlash production as soon as possible, and we appreciate your patience as we manage this short-term disruption.

Importantly, this adjustment does not impact the performance, installation, or quality of the board. VersiCore® Polyiso products continue to meet standard installation practices and remain compliant with existing code and warranty requirements. Versico SecurShield® and SecurShield HD ReadyFlash products remain unaffected by this supply constraint.

We appreciate your continued support of Versico Roofing Systems. If you have any questions regarding this announcement, please contact your local Independent Sales Representative.

Sincerely,



Sergio Shields
Insulation Product Specialist