




- 1. EXTEND VapAir Seal MD TO TOP EDGE OF ROOF INSULATION OR MIN. 2" (5cm).
- 2. HAND ROLL VERTICAL SURFACES WITH 2" (5cm) WIDE PRESSURE ROLLER.
- 3. WHEN VapAir Seal MD HAS TO BE EXTENDED UP THE WALL (TO SEAL WITH EXTERIOR WALL BARRIERS), IT SHOULD BE COVERED WITH INSULATION BOARD (MIN. R-VALUE 6) TO AVOID CONDENSATION AND ALSO TO AVOID UNEQUAL EXPANSION/CONTRACTION OF MEMBRANES. BOARD WILL PROVIDE A SUBSTRATE FOR ROOF MEMBRANE ALSO.
- 4. DIRECT ADHESION OF ROOF MEMBRANE TO VapAirseal MD IS NOT RECOMMENDED.





ROOF TO WALL TRANSITION

	SEE MD-0 (PAGE 1 & 2) FOR ADDITIONAL INFORMATION.	VapA	ir Seal MD
→ VapAir Seal MD → ROOF MEMBRANE CAV-GRIP, CCW-702 OR CCW-702LV	INSTALLATION (PAGE 2 OF 2)	VRX (TI	MD-0
1 → SEE NOTE	A&VB (AIR & VAPOR BARRIER) AS REQUIRED BY DESIGNER		ADHERED A&VB












- 1. REFER TO CARLISLE STANDARD DETAILS FOR ROOF BASE FLASHING.
- 2. CARLISLE SECURSHIELD HD COMPOSITE BOARD, 100 PSI (6.9 KILOPASCAL) COMPRESSIVE STRENGTH [SUGGESTED IN ASHRAE ZONES 6-8 (ZONES B TO D IN CANADA)] OR WHERE CODE REQUIRES FOR c.i. (CONTINUOUS INSULATION).


	SEE MD-0 (PAGE 1 & 2) FOR ADDITIONAL INFORMATION.	VapA	ir Seal MD
→ VapAir Seal MD → ROOF MEMBRANE CAV-GRIP, CCW-702 OR CCW-702LV	PARAPET ON ROOF DECK ROOF A&VB TIE—IN TO WALL A&VB	ZRX (Ti	MD-1.3
1 → SEE NOTE	A&VB (AIR & VAPOR BARRIER) AS REQUIRED BY DESIGNER	1	ADHERED A&VB





- 1. REFER TO CARLISLE STANDARD DETAILS FOR ROOF BASE FLASHING.
- 2. CARLISLE SECURSHIELD HD COMPOSITE BOARD, 100 PSI (6.9 KILOPASCAL) COMPRESSIVE STRENGTH [SUGGESTED IN ASHRAE ZONES 6-8 (ZONES B TO D IN CANADA)] OR WHERE CODE REQUIRES FOR c.i. (CONTINUOUS INSULATION).
- 3. IN HIGH HUMIDITY SPACES, USE VapAir Seal Flashing Foam PER SPECIFICATIONS [SUGGESTED IN ASHRAE ZONES 6-8 (ZONES B-D IN CANADA)].














 REFER TO TYPICAL EXPANSION JOINT DETAIL FOR SELECTED ROOF ASSEMBLY TYPE.





4. ENSURE HOLES ARE OPEN BEFORE THE END OF THE DAY OR PRIOR TO RAIN.



INSULATION INSULATION 2" (5cm) PLUMBER TO ENSURE THAT-2 MIN. REVERSIBLE COLLAR AND DRAIN BOWL ARE 100% AIR AND WATER TIGHT & FLOOD


NOTES:

GASKETS BETWEEN


TESTED.

- 1. EXTEND VapAir Seal MD ONTO DRAIN'S FLAT AREA AND HAND ROLL WITH 2" (5cm) WIDE PRESSURE-ROLLER & ENSURE ANY FISH-MOUTHS ARE SEALED WITH SEALANT.
- 2. USE PRIMER IF SURFACES ARE RUSTY/UNCLEAN/POOR ADHESION IS EXPERIENCED.


	SEE MD-0 (PAGE 1 & 2) FOR ADDITIONAL INFORMATION.	VapA	ir Seal MD
→ VapAir Seal MD → ROOF MEMBRANE CAV-GRIP, CCW-702 OR CCW-702LV	ROOF DRAIN WITH ADJUSTABLE HEIGHT — TYPE A	ZRX (Ti	MD-6.2
1 → SEE NOTE	A&VB (AIR & VAPOR BARRIER) AS REQUIRED BY DESIGNER		ADHERED A&VB




NOTE: REFER TO DETAIL MD-8.3, WHERE MULTIPLE PENETRATIONS EXIST IN ONE AREA




NOTE: REFER TO DETAIL MD-8.3, WHERE MULTIPLE PENETRATIONS EXIST IN ONE AREA








- THE MAXIMUM ALLOWABLE SURFACE TEMPERATURE OF THE PENETRATION SHALL NOT EXCEED 180° F (82° C).
- PENETRATIONS, AIR & VAPOR BARRIER, FLASHING AND METAL (INSIDE POCKET) MUST BE PRIMED WITH EPDM PRIMER PRIOR TO APPLYING POURABLE SEALER. DO NOT PRIME THE BLUE PLASTIC SUPPORT STRIP.
- POURABLE SEALER MUST CONTACT PRIMED PRESSURE-SENSITIVE ELASTOFORM FLASHING AND AIR & VAPOR BARRIER.
- SECUREMENT IS REQUIRED FOR POURABLE SEALER POCKETS WHICH ARE GREATER THAN 18" (46cm) IN DIAMETER. REFER TO SPECIFICATIONS.
- 5. PIPE CLUSTERS MUST HAVE MINIMUM 1" (2.5cm) CLEARANCE BETWEEN PENETRATIONS.
- 22 GAUGE STEEL STRIPS TO FILL GAPS & SUPPORT THE SEALER POCKET, FASTEN INTO DECK.





SEE MD-0 (PAGE 1 & 2) FOR ADDITIONAL INFORMATION. VapAir Seal MD MULTIPLE PENETRATIONS' ROOF MEMBRANE CAV-GRIP, CCW-702 FLASHINGS IN GROUP OR CCW-702LV 1 → SEE NOTE A&VB (AIR & VAPOR BARRIER) AS REQUIRED BY DESIGNER





NOTE: REFER TO DETAIL MD-8.3, WHERE MULTIPLE PENETRATIONS EXIST IN ONE AREA














- 1. SET THRU-WALL STAINLESS STEEL STRIP FLASHING AND EXTEND IT OUT MIN. 3" (7.5cm) (BY OTHERS).
- 2. EXTEND VapAir Seal MD MIN. 6" (15cm) VERTICAL AND FULLY ADHERE TO WALL'S A&VB. WHEN WALL'S A&VB IS NOT INSTALLED YET, THEN ADHERE TO WALL. WALL BARRIER SHALL BE FULLY ADHERED TO VapAir Seal MD.

ABTIERED TO Vaprill South	SEE <u>MD-0 (PAGE 1 & 2)</u> FOR ADDITIONAL INFORMATION.	VapA	ir Seal MD
→ VapAir Seal MD → ROOF MEMBRANE CAV-GRIP, CCW-702 OR CCW-702LV	TIE-IN TO UPPER STOREY WALL	ZRX (Ti	MD-12.1
1 → SEE NOTE	A&VB (AIR & VAPOR BARRIER) AS REQUIRED BY DESIGNER		ADHERED A&VB











PRIOR TO PLACEMENT OF SURE—SEAL CORNER, PEEL OFF THE BLUE POLY RELEASE FILM AND HEAT THE FLASHING SIDE WITH A HEAT GUN. RE—APPLY THE POLY LOOSELY. FOLD THE FLASHING IN HALF.

PLACE SURE—SEAL INSIDE/OUTSIDE CORNER AS SHOWN AND REMOVE RELEASE PAPER. PRESS FOLDED FLASHING TIGHTLY INTO ANGLE CHANGE AND FIRMLY PRESS FLASHING AGAINST THE VERTICAL SURFACE.











PLACE FOLDED FLASHING TIGHTLY INTO ANGLE CHANGE AND FIRMLY PRESS FLASHING ONTO THE DECK FLANGE BY PRESSING THE FLASHING AGAINST THE HORIZONTAL SURFACE.


ROLL WITH A TWO INCH WIDE ROLLER. PAY PARTICULAR ATTENTION TO THE STEP OFFS AND ANGLE CHANGE.

	SEE MD-0 (PAGE 1 & 2) FOR ADDITIONAL INFORMATION.	VapA	ir Seal MD
→ VapAir Seal MD → ROOF MEMBRANE - CAV-GRIP, CCW-702 OR CCW-702LV 1 → SEE NOTE	OUTSIDE CORNER WITH PRE-CUT PRESSURE-SENSITIVE ELASTOFORM EPDM (PAGE 2 OF 2) A&VB (AIR & VAPOR BARRIER) AS REQUIRED BY DESIGNER	ZRX (Ti	MD-15.2C




-01			
DIME	NSIONS	cm	
A	6"	15	ТО
	9"	23	
B	2"	5	MIN.
0	3"	7.5	MAX.







- 1. APPLY EPDM PRIMER TO THE VapAir Seal MD SURFACES PRIOR TO INSTALLING PRESSURE—SENSITIVE FLASHING.
- 2. PRESSURE-SENSITIVE ELASTOFORM FLASHING TO OVERLAP DECK SURFACE 3" (7.5cm) MINIMUM AND EXTEND 2" (5cm) MINIMUM AROUND CORNERS.
- 3. IN COLDER TEMPERATURES, A HEAT GUN MUST BE USED WHEN FORMING PRESSURE—SENSITIVE ELASTOFORM FLASHING.


	SEE MD-0 (PAGE 1 & 2) FOR ADDITIONAL INFORMATION.	VapA	ir Seal MD
J	OUTSIDE CORNER WITH PS EPDM ELASTOFORM FLASHING — OPTION 1	ZRX (Ti	MD-15.2D
→ SEE NOTE	A&VB (AIR & VAPOR BARRIER) AS REQUIRED BY DESIGNER		ADHERED A&VB





USE PRE-CUT T-JOINT COVERS OR CUT A 6"x6" (15X15cm) & 12"x12" (30X30cm) SECTION OF PRESSURE- SENSITIVE ELASTOFORM FLASHING AND ROUND CORNERS.






REPLACE POLY BACKING ON FLASHING. FOLD 6"X6" (15cmX15cm) FLASHING IN HALF WITH ROUNDED PORTION TURNED UP. CENTER ON CORNER & FIRMLY PRESS AGAINST VERTICAL SURFACE.




ROLL & CREASE FLASHING TIGHTLY INTO ANGLE CHANGE & FIRMLY ROLL FLASHING ONTO THE DECK MEMBRANE.

USE HEAT GUN TO WARM THE FLASHING IN COLD WEATHER.



AFTER ADHERING, ROLL WITH A TWO INCH WIDE STEEL HAND ROLLER. PAY PARTICULAR ATTENTION TO THE STEP OFFS AND ANGLE CHANGES.



→ VapAir Seal MD

→ SEE NOTE

1

ROOF MEMBRANE

